

10/820,690

C 2 C



Practitioner's Docket No. Trestain 4.1-3

**PATENT**

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Patent Number: 6,880,693  
Issued: April 19, 2005  
Name of Patentee: Dennis A. Trestain  
Title of Invention: CONVEYOR MOTOR HAVING BELLOWS

Certificate  
JUN 14 2005  
of Correction

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

**REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT  
FOR PTO MISTAKE (37 C.F.R. § 1.322(a))**

**NOTE:** "If such a request for correction was incurred through the fault of the United States Patent and Trademark Office (Office), and is clearly disclosed in the records of the Office, and is accompanied by documentation that unequivocally supports the patentee's assertion(s), a Certificate of Correction will be expeditiously issued. Such supporting documentation can consist of relevant photocopied receipts, manuscript pages, correspondence dated and received by the Office, photocopies of Examiners' responses regarding entry of amendments, or any other validation that supports the patentee's request so that the request can be processed without the patent file." Notice of September, 17, 2002, 1262 OG 96.

1. Attached, in duplicate, is PTO/SB/44 (also Form PTO-1050), with at least one copy being suitable for printing.

**NOTE:** Form PTO-1050 (or PTO/SB/44), using the column and line number in the printed patent, should be used exclusively regardless of the length or complexity of the subject matter. M.P.E.P. § 1485, 7th ed.

**NOTE:** The patent grant should be retained by the patentee. The PTO does not attach the certificate of correction to the patentee's copy of the patent. The patent grant will be returned to the patentee if submitted. M.P.E.P. § 1485, 8th ed.

2. The exact page and line number where the errors are shown correctly in the application file are:

**NOTE:** The exact page and line number where the errors occur in the application file should be identified on the request. However, on form PTO/SB/44, only the column and line number in the printed patent should be used. M.P.E.P., § 1480, 8th Edition.

(Request for Certificate of Correction of Patent For PTO Mistake [14-1]—page 1 of 2)

JUN 16 2005

Column 8, lines 16 and 17 (**Page 15, lines 14 and 15**), "limits witches 44" should be -limit switches 44-.

Column 8, line 50 (**Page 16, line 17**), "38 which: allows the" should be -38 which allows the-.

Column 12, line 50, Claim 36 (**Old Claim 40, lines 12, 13 and 14**), after "of the first" insert -bellows and the predetermined rate of inflation of the second bellows are adjusted depending on which of the first or-.

**3. Please send the Certificate to:**

Name: Mary M. Moyne, McLeod & Moyne, P.C.

Address: 2190 Commons Parkway

Okemos, Michigan 48864

(complete, if applicable)

\_\_\_\_\_  
Signature(s) of patentee(s)

or

\_\_\_\_\_  
(type or print name of assignee)

☐ Assignment recorded on

Reel \_\_\_\_\_

Frame \_\_\_\_\_

  
Signature of assignee or person authorized to sign on behalf of assignee

Mary M. Moyne

(type or print name of authorized person signing)

Attorney of Record

Title of authorized person signing

☐ Recordal of assignment attached

☐ Attached is a "STATEMENT UNDER 37 CFR 3.73(b)," establishing the right of the assignee to take action in this case.

NOTE: "A certificate of correction, under 35 U.S.C. 254, may be issued at the request of the patentee or [the patentee's] assignee." 37 C.F.R. § 1.322(a). The certificate of correction can be signed by the attorney of record who acts on behalf of the inventor(s) or assignee(s).

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,880,693

DATED : April 19, 2005

INVENTOR(S): Dennis A. Trestain

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8, lines 16 and 17, "limits witches 44" should be ~~-limit switches 44-~~.

Column 8, line 50, "38 which: allows the" should be ~~-38 which allows the-~~.

Column 12, line 50, Claim 36, after "of the first" insert ~~-bellows and the predetermined rate of inflation of the second bellows are adjusted depending on which of the first or-~~.

MAILING ADDRESS OF SENDER: Mary M. Moyne  
McLeod & Moyne, P.C.  
2190 Commons Parkway  
Okemos, Michigan 48864

PATENT NO. 6,880,693

No. of additional copies



JUN 16 2005